

## Under Review Notification

**Raised By:** Vanessa Morel

**Product #:** RBW109-3130-82-103

**Date:** 2019.10.23

**Product Name:** TAIL ROTOR BUSHING REMOVAL TOOL

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBW109-3130-82-103	RBW109-3130-82-103 Rev 2	Y	Y	N	Y	Y	N	N	N	19-939	See below

### Description of Issue:

Issues stated on ADR (Fit, manufacturing issues)

RBW109-3130-82-103 and items -1, -3, -5, -7 and -9 must be put on **HOLD** in Plex

RBW109-3130-82-103 Finish good stock can be use as is

Items -1, -3, -5, -7 and -9 must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart

'P" Part must be put on **HOLD** in Plex as well

### Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene